



HC2



HA2



Dry Battery



AC/DC



Multi-Units



Power

4xAAA batteries
Optional 6-9V AC/DC adaptor
(for HA2 and HC2A models)

Capacity

HA2: 60g x 0.001g
HC2A: 300g/600g x 0.01g
HC2B: 1/2/3Kg x 0.1g

S.S Pan (Dia)

dia 60mm (HA2)
95*05mm (HC)

Display

HA2: 45*14mm LCD
HC: 36*13mm LCD

Linearity Error

±2d

Repeatability

±2d

Windshield

HA2 - yes
HC - No

Units

g/ct/gn/dwt

Weight

HA2 - 265g/545g (with box)
HC - 249g

Stainless Steel Pan

HA2 With bubble level and adjustable feet
Auto power off after 3 minutes of inactivity
(if power supply from batteries)
Permanent power on
(if power supply from adapter)
Auto calibration
Low battery indication
Overload indication
HA2 with 20g and 50g calibration weights
HA2 with a tweezers
Dimension: HA2-128*100*60mm
HC-140*102*30mm



Model	HA2	HC3002	HC6002	HC10001	HC20001
Capacity	60g	300g	600g	1000g	2000g
Division	0.001g	0.01g	0.01g	0.1g	0.1g
S.S Pan	60mm	95x95mm	95x95mm	95x95mm	95x95mm

®

PRECISION BALANCE